

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jun 25, 2018 11:29:23 AM MDT
Server Receive Date:	Jun 25, 2018 11:29:35 AM MDT
Reference Number:	20180625-1881470799
Location:	2638 Co Rd 314, Ignacio, CO 81137, USA Jun 25, 2018 11:29:19 AM MDT [View Map]

Information

Name	reclamationtablet
Date	Jun 25, 2018
Location Name (Other)	Simmons a1
Location API (Other)	0506707861
Select State	Colorado
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

cut down thistles on site and removed