

TR 1-23-597
Api# 05-045-06918
Inspection # 689701519



Location photo. No sign on well or location.

TR 1-23-597
Api# 05-045-06918
Inspection # 689701519



No signs at wells

TR 1-23-597
Api# 05-045-06918
Inspection # 689701519



Temporary abandoned well. No well sign.

TR 1-23-597
Api# 05-045-06918
Inspection # 689701519



East edge of location fenced reclaim work.