

Inspection Photos
Location Name: McIntyre Flowback Pits #3 and #4
Facility ID: 421066



Pit Facility ID #418791 overview.



Pit Facility ID #418790.

Inspection Photos
Location Name: McIntyre Flowback Pits #3 and #4
Facility ID: 421066



Pit Facility ID #418791.



Pit Facility ID #418790.

Inspection Photos

Location Name: McIntyre Flowback Pits #3 and #4

Facility ID: 421066



Lower pit with Federal 11-90-26 #1 production equipment stored nearby.



10+' fluid level on upper pit gauge stick.

Inspection Photos

Location Name: McIntyre Flowback Pits #3 and #4

Facility ID: 421066



Oil present in northern corner of upper pit.



Federal 11-90-26 #1 production equipment stored on site.

Inspection Photos
Location Name: McIntyre Flowback Pits #3 and #4
Facility ID: 421066



Production equipment from the Federal 11-90-26 #1 in SW corner of location.



Fluid level is almost to the 8' mark on the gauge stick in the lower pit.