

**Inspection Photos**  
**Location Name: Deer Creek State 1 (16-4-91)**  
**API: 05-081-06370**



**Photo 1. Overview of location taken at entrance facing west.**



**Photo 2. Example of overgrown section of access road.**

**Inspection Photos**  
**Location Name: Deer Creek State 1 (16-4-91)**  
**API: 05-081-06370**



**Photo 3. Example of rutted section of access road. Ruts 12-20" deep.**



**Photo 4. Example of rutted section of access road.**