



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jun 28, 2018 11:33:53 AM MDT
Server Receive Date:	Jun 28, 2018 11:34:03 AM MDT
Reference Number:	20180628-1881801724
Location:	Unnamed Road, Ignacio, CO 81137, USA Jun 28, 2018 11:33:27 AM MDT [View Map]

Information

Name	reclamationtablet
Date	Jun 28, 2018
Location Name (Other)	Tillman Burch 2
Location API (Other)	0506708639
Select State	Colorado
Action Complete	Install Rock Run Down Clean up Operator Debris Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

built rock rundowns and removed old fincing and weeds