

Inspection Photos
Location Name: Federal 11-90-26 #1
API: 05-051-06060



Federal 11-90-26 #1 location photo.

Federal 11-90-26 #1 well head.

Inspection Photos
Location Name: Federal 11-90-26 #1
API: 05-051-06060



Oil leak on location.



Lube/hydraulic oil leaks on pad.

Inspection Photos
Location Name: Federal 11-90-26 #1
API: 05-051-06060



Location berm on southern edge of pad.



Silt fence in disrepair.