

Inspection Photos  
Location Name: PCW 44-8  
Facility ID: 217612



Photo 1. Wellhead



Photo 2. Calibration out of date