

Inspection Photos

API#081-07116

Operator: Matagorda Production

Inspection Number: 674104501

Inspection Date: 7/8/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1: April 22, 2017

Photo#2: June 8, 2018

Views of un-reclaimed Access Road from County Rd to Northeast into Location.

June 8, 2018



Photo#3:

Scotch thistle and Houndstongue, B List Noxious weeds and Cheat grass, C List Noxious Weed established along Access Road.



Photo #4:

June 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Matagorda PA Morgan Creek API#081-07116



Photo#5:
Debris remains on Location.

June 8, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Matagorda PA Morgan Creek API#081-07116