

# *Inspection Photos*

*Loc#322004*

*Operator: Gunnison Energy*

*Inspection Number: 674104506*

*Inspection Date: 6/24/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from Entry to Northwest.

June 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Gunnison Energy Lone Pine Loc#322004



Photo#2:

Well head is set in Open Cellar with no cover to prevent entrapment of Wildlife. At time of Inspection Cellar was filled with water..

June 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Gunnison Energy Lone Pine Loc#322004



Photo#3:

Heavier Thistle growth on Soil Pile at Southeast corner of site .

June 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Gunnison Energy Lone Pine Loc#322004



Photo#4:

What may have been Pit is fenced off at Northwest corner of Location.

June 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Gunnison Energy Lone Pine Loc#322004



Photo#:  
View to South along Fill Slope.

June 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Gunnison Energy Lone Pine Loc#322004



Photo#6:

View of Cut Slope; inserts close-ups of Slough feature and Thistle growth. .

June 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Gunnison Energy Lone Pine Loc#322004