

Inspection Photos

Loc#381443

Operator: Gunnison Energy

Inspection Number: 674104508

Inspection Date: 6/24/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from South to Northwest.

June 24, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy Steven's Gulch Loc#381443



Photo#2:
Overview of Location from top of Cut slope to Southeast.

June 24, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy Steven's Gulch Loc#381443



Photo#3:

View over Pit area at Southwest corner of Location.

June 24, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy Steven's Gulch Loc#381443



Photo#4:

Thistle & Oxeye daisy noted on Access Road & Location.



Photo#5:

June 24, 2018