

Inspection Photos  
Location Name: BCU Pad 16P  
Location ID: 334461



**Photo 1. Trash at wellheads**



**Photo 2. Trash, debris and stored equipment on edge of location.**