

HALLIBURTON

iCem[®] Service

EXTRACTION OIL & GAS

Date: Monday, January 29, 2018

Hergert South 35W-15-5N Surface

Job Date: Sunday, January 28, 2018

Sincerely,

Bryce Hinsch

Legal Notice

Warning Disclaimer

Although the information contained in this report is based on sound engineering practices, the copyright owner(s) does (do) not accept any responsibility whatsoever, in negligence or otherwise, for any loss or damage arising from the possession or use of the report whether in terms of correctness or otherwise. The application, therefore, by the user of this report or any part thereof, is solely at the user's own risk.

Limitations of Liability

Except as expressly set forth herein, there are no representations or warranties by Halliburton, express or implied, including implied warranties of merchantability and/or fitness for a particular purpose. In no event will Halliburton or its suppliers be liable for consequential, incidental, special, punitive or exemplary damages (including, without limitation, loss of data, profits, use of hardware, or software). Customer accepts full responsibility for any investment made based on results from the Software. Any interpretations, analyses or modeling of any data, including, but not limited to Customer data, and any recommendation or decisions based upon such interpretations, analyses or modeling are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and assumptions are not infallible, and with respect to which professional may differ. Accordingly, Halliburton cannot and does not warrant the accuracy, correctness or completeness of any such interpretation, recommendation, modeling or other products of the Software Product. As such, any interpretation, recommendation or modeling resulting from the Software for the purpose of any drilling, well treatment, production or financial decision will be at the sole risk of Customer. Under no circumstances will Halliburton or its suppliers be liable for any damages.

Table of Contents

1.0	Cementing Job Summary	4
1.1	Executive Summary	4
2.0	Real-Time Job Summary	7
2.1	Job Event Log	7
3.0	Attachments.....	10
3.1	CUSTOM RESULTS – JOB CHART WITH EVENTS	10

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Hergert South 35W-15-5N** cement **surface** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 6 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton [Fort Lupton]

HALLIBURTON

Cementing Job Summary

The Road to Excellence Starts with Safety

Sold To #: 369404		Ship To #: 3840276		Quote #:		Sales Order #: 0904588225						
Customer: EXTRACTION OIL & GAS -				Customer Rep: Shawn McIntyre								
Well Name: HERGERT SOUTH			Well #: 35W-15-5N			API/UWI #: 05-123-45901-00						
Field: WATTENBERG		City (SAP): SEVERANCE		County/Parish: WELD		State: COLORADO						
Legal Description: NE SE-35-7N-67W-2272FSL-647FEL												
Contractor: Cartell 44				Rig/Platform Name/Num: Cartel 41								
Job BOM: 7521 7521												
Well Type: HORIZONTAL OIL												
Sales Person: HALAMERICA\HX38199				Srcv Supervisor: Bradley Hinkle								
Job												
Formation Name												
Formation Depth (MD)		Top			Bottom							
Form Type					BHST							
Job depth MD		1550ft			Job Depth TVD		1550ft					
Water Depth					Wk Ht Above Floor							
Perforation Depth (MD)		From			To							
Well Data												
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft		
Casing	0	9.625	8.921	36	8 RD	J-55	0	1550	0	1550		
Open Hole Section			13.5				0	1570	0	1570		
Tools and Accessories												
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make			
Guide Shoe	9.625					Top Plug	9.625	1	HES			
Float Shoe	9.625	1		1550		Bottom Plug	9.625		HES			
Float Collar	9.625	1		1505		SSR plug set	9.625		HES			
Insert Float	9.625					Plug Container	9.625	1	HES			
Stage Tool	9.625					Centralizers	9.625		HES			
Fluid Data												
Stage/Plug #: 1												
Fluid #	Stage Type	Fluid Name			Qty	Qty UoM	Mixing Density lbm/gal	Yield ft ³ /sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
1	Spacer	Fresh Water			10	bbl	8.33			4.5		
Fluid #	Stage Type	Fluid Name			Qty	Qty UoM	Mixing Density lbm/gal	Yield ft ³ /sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
2	Spacer	Red Dye Water			10	bbl	8.33			4.5		

HALLIBURTON

Cementing Job Summary

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft ³ /sack	Mix Fluid Gal	Rate bbl/mi n	Total Mix Fluid Gal	
3	Cement	SWIFTCEM	525	sack	13.5	1.74		6	9.2	
4	Displacement	Fresh Water	117	bbl	8.33			6		
Cement Left In Pipe		Amount	42 ft		Reason			Shoe Joint		
Mix Water:		pH 6	Mix Water Chloride:		0 ppm		Mix Water Temperature:			67 °F
Cement Temperature:		## °F °C		Plug Displaced by:		## lb/gal kg/m ³ XXXX		Disp. Temperature:		## °F °C
Plug Bumped?		Yes		Bump Pressure:		506 psi		Floats Held?		Yes
Cement Returns:		5 bbl		Returns Density:		## lb/gal kg/m ³		Returns Temperature:		## °F °C
Comment 6 bbls cement to surface.										

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	PS Pump Press (psi)	DH Density (ppg)	Comb Pump Rate (bbl/min)	Comments
Event	1	Call Out	Call Out	1/23/2018	06:00:00	USER				Crew called for an on location of 1200. Crew was Bradley Hinkle, Mitchell Camper, Peter Ginsberg, Todd Reeve and Brian Jackson.
Event	2	Depart Shop for Location	Depart Shop for Location	1/23/2018	07:00:00	USER				Pre-journey safety meeting.
Event	3	Arrive at Location from Service Center	Arrive at Location from Service Center	1/23/2018	08:00:00	USER				Perform a site assessment and pre-rig up safety meeting.
Event	4	Safety Meeting	Safety Meeting	1/24/2018	03:00:00	USER	2.00	0.00	0.00	Pre-job safety meeting. Rid crew did not participate.
Event	5	Other	Job Numbers	1/24/2018	03:30:00	USER	-3.00	0.00	0.00	TD: 1570. TP: 1550. FC: 1505. 9.625" 36# casing inside a 13.5" OH. Mud weight at 8.4 ppg.
Event	6	Start Job	Start Job	1/24/2018	03:35:43	COM4	30.00	8.48	0.00	
Event	7	Test Lines	Test Lines	1/24/2018	03:38:36	COM4	1005.00	9.01	0.00	Pressure test lines with a 500 psi electronic kick-out test.
Event	8	Pump Spacer 1	Pump Spacer 1	1/24/2018	03:42:06	COM4	48.00	8.77	0.00	Pump 10 bbls fresh water.
Event	9	Pump Spacer 2	Pump Spacer 2	1/24/2018	03:44:52	COM4	225.00	9.05	5.50	Pump 10 bbls red dye water.
Event	10	Pump Cement	Pump Cement	1/24/2018	03:51:58	COM4	64.00	8.97	1.60	Pump 162 bbls (525 sacks, 1.74 yield, 9.2 gal/sk) SwiftCem mixed at 13.5 ppg. Density verified by

										pressurized scales.
Event	11	Check Weight	Check weight	1/24/2018	03:54:05	COM4	239.00	13.56	6.10	Cement weighed at 13.5 ppg.
Event	12	Shutdown	Shutdown	1/24/2018	04:21:01	COM4	22.00	0.14	0.00	
Event	13	Drop Top Plug	Drop Top Plug	1/24/2018	04:23:11	COM4	29.00	13.73	0.00	Top plug preloaded. Witnessed by customer.
Event	14	Pump Displacement	Pump Displacement	1/24/2018	04:23:19	COM4	31.00	13.76	0.00	Pump 117 bbls fresh water. Good returns throughout. Returns coming up through conductor and mouse hole. Displacement rate slowed to minimize washout. 6 bbls cement to surface.
Event	15	Bump Plug	Bump Plug	1/24/2018	04:49:18	COM4	764.00	7.78	0.20	Bump plug at 506 psi and increased 500 psi over.
Event	16	Pressure Up Well	Pressure Up Well	1/24/2018	04:51:21	COM4	1489.00	7.78	0.00	Increase pressure to 1500 psi for a 5 minute casing test.
Event	17	Check Floats	Check Floats	1/24/2018	04:56:36	USER	102.00	7.63	0.00	Floats held. 1 bbl back.
Event	18	End Job	End Job	1/24/2018	04:57:10	COM4	23.00	7.62	0.00	
Event	19	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	1/24/2018	05:00:00	USER	14.00	7.58	0.00	Pre-rig down safety meeting.
Event	20	Depart Location for Service Center or Other Site	Depart Location for Service Center or Other Site	1/24/2018	06:00:00	USER				Pre-journey safety meeting.

3.0 Attachments

3.1 CUSTOM RESULTS – JOB CHART WITH EVENTS

