

Inspection Photos  
Location Name: ROMERO 23-14  
Facility ID: 257735



Photo 1. Wellhead



Photo 2. Location sign

Inspection Photos  
Location Name: ROMERO 23-14  
Facility ID: 257735



Photo 3. Cracked 1" valve



Photo 3. Better view of crack in valve.