

Inspection Photos

API#029-06090

Operator: Gunnison Energy

Inspection Number: 674104514

Inspection Date: 6/25/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View over Location from Entry to East.

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy AL Jordan & Scott API#029-06090



Photo#2:

View from Southeast corner of Location to Northwest; access road entry indicated by arrow.

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy AL Jordan & Scott API#029-06090



Photo#3:
View along Fill Slope to Southwest.

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy AL Jordan & Scott API#029-06090



Photo#4:
View of Cut Slope at North side of Location.

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy AL Jordan & Scott API#029-06090



Photo#5:
Thistle established on Northeast slope.

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy AL Jordan & Scott API#029-06090



Photo#6:
Looking West out access road that leads to Highway 65

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy AL Jordan & Scott API#029-06090



Photo#7:
Noxious weeds established along access road.



Photo#8:

June 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Gunnison Energy AL Jordan & Scott API#029-06090