

**Inspection Photo
Couey Federal
API # 045-12526
Inspection # 689301435**



Location Photo #1



**Location Photo #2, No berm around
produced water tank**

**Inspection Photo
Couey Federal
API # 045-12526
Inspection # 689301435**



**Location Photo #3, No berm around
produced water tank**



**Location Photo #4, No berm around
produced water tank**

Inspection Photo
Couey Federal 23-10
API # 045-12526
Inspection # 689301435



Location Photo #5, Sediment being moved off location. West side near entrance



Location Photo #6, Sediment being moved off location

**Inspection Photo
Couey Federal
API # 045-12526
Inspection # 689301435**



Location Photo #7, Sediment being moved off location



Location Photo #8, Sediment being moved off location