

**Inspection Photo  
Couey 24-10B  
API # 045-14863  
Inspection # 689301437**



**Location Photo #1**



**Location Photo #2, sign peeling off of tank**

**Inspection Photo  
Couey 24-10B  
API # 045-14863  
Inspection # 689301437**



**Location Photo #3, Sign information incorrect**



**Location Photo #4, No berm around tank at wellhead**