

Inspection Photo
Kell 35-3
API # 045-07583
Inspection # 689301449



Location Photo #1



Location Photo #2, weeds around Wellhead

Inspection Photo
Kell 35-3
API # 045-07583
Inspection # 689301449



Location Photo #3, weeds in and around Wellhead



Location Photo #4, weeds near Separator