



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of berms and diversion in the western project area from the southwestern corner facing northward. Culverts need to be removed.



Photo 3. View of equipment storage in the southern project area.