

# *Inspection Photos*

*Loc#334464*

*Operator: Laramie*

*Inspection Number: 674104530*

*Inspection Date: 6/28/2018*





Photo#1:  
View over Location to North.

June 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie N Vega Loc#334464



**Photo#2:**  
Erosion of Cut slopes and Sediment Run on to Location is still occurring.



**Photo#3:**  
Erosion of Cut slopes and Sediment Run on to Location is still occurring.

June 28, 2018



Photo#4:  
Liner has become debris.  
\*



Photo#5:  
Dump area for materials, perhaps sediment clean  
outs.

June 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie N Vega Loc#334464



Photo#6:  
Noxious weed, Musk Thistle is scattered over Location & along Access Road.




Photo#7:

June 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie N Vega Loc#334464



Photo#8: Aerial 2009 COGCC Maps

Photo#9: Aerial 2017 COGCC Maps

Areas no longer needed for Use have not been reclaimed for Interim Reclamation.

June 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie N Vega Loc#334464