

Inspection Photos
Location Name: Midwest Govt 1
API: 05-081-05265



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Incomplete battery sign.

Inspection Photos
Location Name: Midwest Govt 1
API: 05-081-05265



Photo 3. Noxious weeds on location.



Photo 4. Pit.

Inspection Photos
Location Name: Midwest Govt 1
API: 05-081-05265



Photo 5. Gauge hatch open.



Photo 6. Stained soil at tank base.

Inspection Photos
Location Name: Midwest Govt 1
API: 05-081-05265



Photo 7. Stained soil at tank loadout.



Photo 8. Stained soil at tank base.

Inspection Photos
Location Name: Midwest Govt 1
API: 05-081-05265



Photo 9. Stained soil, trash, vegetation in berm.



Photo 10. No labels on tanks. Vegetation in and on berm.