

Inspection Photos
Location Name: Black Mountain-Federal A-
1
API: 05-081-06423



Photo 1. Overview of location taken at entrance facing northwest.

Inspection Photos
Location Name: Black Mountain-Federal A-
1
API: 05-081-06423



Photo 2. Unmarked riser not LOTO.



Photo 3. No capacity on produced water tank.