

Inspection Photos  
Location Name: Maudlin Gulch Unit 27  
API: 05-081-06572



**Photo 1. Overview of location taken at entrance facing northwest.**



**Photo 2. Stained soil at wellhead.**