

Inspection Photo
KRK 7-14 (N7E)
API # 045-07232
Inspection # 689301465



Location Photo #1



Location Photo #2, Housekeeping issue, weeds.

Inspection Photo
KRK 7-14 (N7E)
API # 045-07232
Inspection # 689301465



Location Photo #3, Housekeeping issue, weeds.



Location Photo #4, Weeds on location

Inspection Photo
KRK 7-14 (N7E)
API # 045-07232
Inspection # 689301465



Location Photo #5, weeds near entrance of location