

**Inspection Photo**  
**KRK 7-15C (07EB)**  
**API # 045-08921**  
**Inspection # 689301467**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo  
KRR 7-15C (07EB)  
API # 045-08921  
Inspection # 689301467**



**Location Photo #3, House keeping, weeds on location**



**Location Photo #4, Housekeeping issue, weeds.**

**Inspection Photo**  
**KRK 7-15C (07EB)**  
**API # 045-08921**  
**Inspection # 689301467**



**Location Photo #5, unused equipment near wellhead**