

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/06/2018

Submitted Date:

07/06/2018

Document Number:

677900685**FIELD INSPECTION FORM**
 Loc ID 415476 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 332-3585	gjones@augustusenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415688	WELL	PR	05/29/2010	GW	125-11747	Kerbs L&C 17-03	PR

General Comment:Routine Inspection

Location

Lease Road:			
Type	Other		
comment:	Trail through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Progressive Cavity	# 1		
Comment:	Weatherford cavity pump		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Control panel		
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	415688	Type:	WELL	API Number:	125-11747	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central meter run for (Kerbs 17-02, 17-03, 17-04, 17-05, 17-06, 17-07) 1955' SSE								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT