



## Form Information

|                      |   |
|----------------------|---|
| Form Name:           | <b>Compliance Follow Up Form</b>  |
| Submitter Name:      | Reclamation Tablet (reclamationtablet)  |
| Submission Date:     | Jul 9, 2018 10:59:59 AM MDT   |
| Server Receive Date: | Jul 9, 2018 11:00:15 AM MDT   |
| Reference Number:    | 20180709-1882531180   |
| Location:            | 4820 Co Rd 523, Bayfield, CO 81122, USA<br>Jul 9, 2018 10:59:45 AM MDT [ <a href="#">View Map</a> ] |

## Information

|   |   |
|---|---|
| Name  | reclamationtablet   |
| Date  | Jul 9, 2018   |
| Optional - Type Part of the Run Number or Lateral to Filter for Next Question | state mz 2  |
| Location Name (Other)   | state mz 2  |
| Select State  | Colorado  |
| Work type   | COGCC Inspection AR   |
| Action Complete   | Clean up Operator Debris<br>Clean Up Weed Debris<br>Clean Up Contaminated Soils |

Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

