

# Final Reclamation Inspection

June 27, 2018

Operator: SRC ENERGY INC- #10311

API: 05-123-20035

Inspection Document #: 682403747

Weld County, CO

SWSW Section 1 T5N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources



**Photo 1.** Photo taken from the well location, facing East. Photo illustrates that the well location has not been properly contoured and there could also be subsidence issues.

Inspection Photos  
Location Name: HERTZKE #1-33  
API: 05-123-20035



**Photo 2.** Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: HERTZKE #1-33  
API: 05-123-20035



**Photo 3.** Photo taken from a portion of the well location access road, facing South. Access road will remain in-process until it meet Rule 1004 vegetative standards.



**Photo 4.** Reference photo taken west of the well location access road, facing South. See comments under Photo 3.