

Inspection Photos  
Location Name: Vega Pad 14  
Location ID: 334443



Photo 1. Location sign.



Photo 2. Riser LOTO.

Inspection Photos  
Well Name: PVGP 0992-18-09W  
Location ID: 311747



**Photo 3. Cellar has been filled in.**



**Photo 2. Irrigation water no longer bypassing stormwater BMPs.**