

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2018

Submitted Date:

07/11/2018

Document Number:

689401455**FIELD INSPECTION FORM**

|  |                                    |   |                   |   |
|--|------------------------------------|---|-------------------|---|
| Loc ID<br>334487   | Inspector Name:<br>CONKLIN, CURTIS | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>15 Number of Comments<br>1 Number of Corrective Actions<br><input checked="" type="checkbox"/> Corrective Action Response Requested |
| <b>Operator Information:</b><br>OGCC Operator Number: <u>10433</u><br>Name of Operator: <u>LARAMIE ENERGY LLC</u><br>Address: <u>1401 SEVENTEENTH STREET #1400</u><br>City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> |                                    |   |                   |   |
|  |                                    |   |                   |   |
|  |                                    |   |                   |   |

**Contact Information:**

| Contact Name       | Phone | Email                                 | Comment                         |
|--------------------|-------|---------------------------------------|---------------------------------|
| Laramie Energy LLC |       | cogccnotifications@laramie-energy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 290618      | WELL | PR     | 05/16/2007  | GW         | 077-09287 | NORTH VEGA 26-221 | PR          |
| 291546      | WELL | PR     | 11/13/2012  | GW         | 077-09361 | DELTA 26-231      | PR          |
| 291547      | WELL | PR     | 07/24/2007  | GW         | 077-09360 | DELTA 26-241      | PR          |
| 291548      | WELL | PR     | 07/24/2007  | GW         | 077-09359 | DELTA 26-224      | PR          |
| 291549      | WELL | PR     | 07/24/2007  | GW         | 077-09358 | DELTA 26-141      | PR          |
| 291550      | WELL | PR     | 07/24/2007  | GW         | 077-09357 | DELTA 26-134      | PR          |
| 291551      | WELL | PR     | 07/24/2007  | GW         | 077-09356 | DELTA 26-131      | PR          |
| 291552      | WELL | PR     | 07/24/2007  | GW         | 077-09355 | DELTA 26-124      | PR          |
| 291553      | WELL | PR     | 07/24/2007  | GW         | 077-09354 | DELTA 26-121      | PR          |

**General Comment:**

This is a follow up inspection to FIR Doc#689400128. Any corrective actions not addressed from previous inspections are still applicable.



**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: [Posted Emergency Contact Number 1-800-891-6191](#)

Corrective Action:

Date:

**Good Housekeeping:**

|                    |  |       |                            |
|--------------------|--|-------|----------------------------|
| Type               | UNUSED EQUIPMENT   |       |                            |
| Comment:           | <a href="#">Riser mentioned on previous inspection had been LOTO. Corrective action from previous inspection has been met. LOTO tags have been torn off.</a> |       |                            |
| Corrective Action: | <a href="#">Replace missing LOTO tags.</a>   | Date: | <a href="#">07/13/2018</a> |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |                        |       |  |
|--------------------|------------------------|-------|--|
| Type               | WELLHEAD               |       |  |
| Comment:           | <a href="#">Panels</a> |       |  |
| Corrective Action: |                        | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL           | 1 | <50 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|------|----------|---------------------|---------------------|-------------|



|                    |          |                     |                     |             |        |
|--------------------|----------|---------------------|---------------------|-------------|--------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS |
| CONDENSATE         | 2        | 400 BBLs            | HEATED STEEL AST    |             | ,      |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| <u>Paint</u>       |          |                     |                     |             |        |
| Condition          | Adequate |                     |                     |             |        |
| Other (Content)    |          |                     |                     |             |        |
| Other (Capacity)   |          |                     |                     |             |        |
| Other (Type)       |          |                     |                     |             |        |
| <u>Berms</u>       |          |                     |                     |             |        |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS |
| CONDENSATE         | 2        | 400 BBLs            | STEEL AST           |             | ,      |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| <u>Paint</u>       |          |                     |                     |             |        |
| Condition          | Adequate |                     |                     |             |        |
| Other (Content)    |          |                     |                     |             |        |
| Other (Capacity)   |          |                     |                     |             |        |
| Other (Type)       |          |                     |                     |             |        |
| <u>Berms</u>       |          |                     |                     |             |        |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| <u>Venting:</u>    |          |                     |                     |             |        |
| Yes/No             | NO       |                     |                     |             |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| <u>Flaring:</u>    |          |                     |                     |             |        |
| Type               |          |                     |                     |             |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |



| Inspected Facilities  |               |       |      |             |           |         |    |               |    |
|-----------------------|---------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 290618        | Type: | WELL | API Number: | 077-09287 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291546        | Type: | WELL | API Number: | 077-09361 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291547        | Type: | WELL | API Number: | 077-09360 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291548        | Type: | WELL | API Number: | 077-09359 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291549        | Type: | WELL | API Number: | 077-09358 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291550        | Type: | WELL | API Number: | 077-09357 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291551        | Type: | WELL | API Number: | 077-09356 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291552        | Type: | WELL | API Number: | 077-09355 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |               |       |      |             |           |         |    |               |    |
| Comment:              | PR w/ Plunger |       |      |             |           |         |    |               |    |
| Corrective Action:    |               |       |      |             |           | Date:   |    |               |    |



|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 291553 | Type: | WELL | API Number: | 077-09354 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

Producing Well

Comment: PR w/ Plunger

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|



**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Stormwater erosion appears to be controlled on the location at this time.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 689401456    | NVega 3A Pad Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520262">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520262</a> |