

Inspection Photos
Location Name: GREAT WESTERN-66N67W
27SSW
Location ID: 333033



27-14 Wellhead. Corrective Action: Remove trash to comply with 603.f



27-24 Wellhead. Corrective Action: Remove trash to comply with 603.f

Inspection Photos
Location Name: GREAT WESTERN-66N67W
27SSW
Location ID: 333033



27-53 Wellhead. Corrective Action: Remove trash to comply with 603.f



27-13 Wellhead. Corrective Action: Remove trash to comply with 603.f



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN-66N67W
27SSW

Location ID: 333033



Separators, ECD, and meter runs



Tank battery. **Corrective Action: Install NFPA label to comply with 210.d**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources