

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/03/2018

Submitted Date:

07/05/2018

Document Number:

682600515

FIELD INSPECTION FORM

Loc ID 413766 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10084
Name of Operator: PIONEER NATURAL RESOURCES USA INC
Address: 5205 N O'CONNOR BLVD STE 200
City: IRVING State: TX Zip: 75039

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
411856	WELL	PR	09/16/2011	GW	071-09766	Pointer 43-25	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Small spill of fluid around wellhead had a hydrocarbon odor indicating a possible spill during well service. Spill volume did not appear to be reportable under Rule 906.

Photos attached to document status of location during inspection.

Inspected Facilities

Facility ID: 411856 Type: WELL API Number: 071-09766 Status: PR Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OTHER E&P WASTE Estimated Spill Volume: _____

Comment: Small spill of fluid around wellhead had a hydrocarbon odor indicating a possible spill during well service. Spill volume did not appear to be reportable under Rule 906.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Date: 08/05/2018

Reportable: NO GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401694525	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514940
682600516	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514934