

Inspection Photos
Location Name: Nielson #4
API: 05-007-06117



300 bbl. AST for Nielson #4 in shared earthen secondary containment berm with Albert Martinez #1 ASTs.



Nielson #4 pump jack and well head.

Inspection Photos
Location Name: Nielson #4
API: 05-007-06117



Stained soil and well head.



Crude oil tank battery for Albert Martinez #1 and Nielson #4.