

## Inspection Photos

Location Name: Cache - 66N63W / 8SWSE

Location #: 306312



**Photo #1**

Cache 8-34 (API 05-123-24412) wellhead.

**No sign or emergency contact information**



**Photo #2**

Cache 8-34, 8-13, 8-23, 8-24, 8-33,  
Cornish 8-53 Battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Cache - 66N63W / 8SWSE

Location #: 306312



**Photo #3**

East separator doghouse.

**Trash**



**Photo #4**

Compressor

**Stained soil**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources