

Inspection Photos

07/11/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 447525

Inspection Doc. Number: 682503564
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 447525



Photo 1: Photo taken from the southeast end of the location, facing west. Photo of location.



Photo 2: Photo taken from the southeast end of the location, facing northwest. Photo of location.



Photo 3: Photo taken from the north end of the location. Previous inspection required management and removal of these noxious weeds.

Photo shows Diffuse Knapweed (lighter, grey-green plants, white colored flowers) remains prevalent throughout the location and have not been managed/removed. Plants are flowering or have matured and preparing to seed.



Photo 4: Photo taken from the south end of the location. See comments under photo 3.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 447525



Photo 15: Photo taken from the west end of the location, facing north. See comments under photo 3.