

Inspection Photos

07/11/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 330359

Inspection Doc. Number: 682503568
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the access road, facing east. Previous inspection required management and removal of noxious weeds.



Photo 2: Photo taken from the access road. See comments under photo 1.

Photo shows Diffuse Knapweed (lighter, grey-green plants, white colored flowers) remains prevalent on location and have not been managed/removed. Plants are flowering or have matured and are preparing to seed.