

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/13/2018

Submitted Date:

07/15/2018

Document Number:

688302227

FIELD INSPECTION FORM

Loc ID 433299 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 19160
Name of Operator: CONOCO PHILLIPS COMPANY
Address: P O BOX 2197
City: HOUSTON State: TX Zip: 77252-

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
ConocoPhillips		COPColoradoReg@conocophillips.com	
Yu, Liang	281-467-5712	Liang.Yu@conocophillips.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433755	WELL	PR	01/30/2014	OW	005-07212	Cline 4-64 2 1H	SI

General Comment:

Produced Water Spill at lined tank battery inspection from a call received on 7/12/2018 from operator of ~53 BBIs. Well was shut in, spill was cleaned up, tank empty and workers were beginning for fix hole in tank by bottom valve (see attached photo). Landowner and Arapahoe Cty LGD would be contacted. Tank is located ~500' SE of West Sand Creek and there is shallow groundwater in the area.

Inspected Facilities

Facility ID: 433755 Type: WELL API Number: 005-07212 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: Produced water tank (400 bbls) leaked from a hole at the bottom of the tank.

Corrective Action: Conctact COGCC EPS. Date: 07/16/2018

Reportable: YES GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688302235	ConocoPhillips Cline 4-64 2 1H	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4523733