

**Inspection Photo**  
**Bernklau RMV 108-4**  
**API # 045-07179**  
**Inspection # 689301489**



**Location Photo #1**



**Location Photo #2**



**Inspection Photo**  
**Bernklau RMV 108-4**  
**API # 045-07179**  
**Inspection # 689301489**



**Location Photo #3, Looking North**



**Location Photo #4, North end of location,  
large amount of weeds**



**Inspection Photo**  
**Bernklau RMV 108-4**  
**API # 045-07179**  
**Inspection # 689301489**



**Location Photo #5, Old weeds that were not removed**



**Location Photo #6, pile of weeds behind tank Battery**



**Inspection Photo**  
**Bernklau RMV 108-4**  
**API # 045-07179**  
**Inspection # 689301489**



**Location Photo #7, spot sprayed weeds**



**Location Photo #8, spot sprayed weeds**

**Inspection Photo  
Bernklau RMV 108-4  
API # 045-07179  
Inspection # 689301489**



**Location Photo #9, looking south at wellheads.**

**Location Photo #2**

