

Inspection Photos
Location Name: Sandhills Federal 14-15
API: 05-081-06896



Photo 1. Overview of wellhead portion of location taken at entrance facing northeast.



Photo 2. Overview of production area of location taken at entrance facing southeast.

Inspection Photos
Location Name: Sandhills Federal 14-15
API: 05-081-06896



Photo 3. No capacity on condensate tank.



Photo 4. 1 – 2" steel riser not marked or LOTO.