

Inspection Photos
Location Name: Baggs Land and Cattle 1
API: 05-081-06029



Photo 1. Overview of location taken at entrance facing north.

Inspection Photos
Location Name: Baggs Land and Cattle 1
API: 05-081-06029



Photo 2. Riser not marked or LOTO.



Photo 3. Left hand tank without label.