

API 087-05111

WELL SITE INSPECTION FORM

087-05111



99999999



Well Name Lacey #1 API Number 05 - 001 - 08184  
 Operator Griffin 35998 Permit # 821319  
 Location SESW 28-15-58 County Adams  
 Field Hoffman Creek Inspector Binkley  
 AL/PA/DA Inspection Results: Well Status:  
 Pass (Y)      Fail (N) X Date 11-16-90 FN      FD      WO      PR      SI     

Date of Inspection Before/During Drilling                     

Surf. Csg. Size      Setting Depth      Cmt. Vol.      WOC time       
 Consistent with APD casing Program? YES      NO      Returns       
 Rig      BOP'S      Contact     

Date of Inspection Before/During/After Completion                     

Prod. Csg. Set?      Completion Rig/Activity       
 Drilling Pits: Closed      Open      Wellhead Installed:      Sign: Yes      No       
 Tank ID: Yes      No      N/A      Skim Tank/Pit:      Prod. Tanks: ( )      BBLs  
 Equipment      Meter Run: Yes      No       
 Bradenhead Press:      Fluid: No      Yes      Type      Well Cat.     

## AL/PA/DA Inspection

Date Plugged: 8-15-88 Date Permit Expired:                       
 Hole Plugged: Yes X No      Pits Backfilled: Yes      No X Skim  
 Material Buried: Yes      No X N/A      Site Clean: Yes      No X Battery  
 Bond Release OK: Yes      No X Fed      Hole Marker: Yes      No X

Date of Safety/Status Inspection                     

Comments: SKIM pit & cover, risers at tank battery, steps  
to tank, drums, misc junk metal, Fencing.

Drill # not Y in NAT



00021167

Violations: Yes      No      Notice Sent: Yes      No      Date Sent: