

# Inspection Photos

07/17/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 323695

Inspection Doc. Number: 682503583

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 323695



**Photo 1:** Photo taken from the north end of the battery location, facing south. Photo shows battery remains predominantly bare and exposed soil, or vegetated by undesirable weedy plant species. FIRR #401471165 states that corrective action has been addressed, that "location was ripped and cross-ripped, disc and seeded with alfalfa on November 22, 2017". Unable to find evidence of crop establishment.



**Photo 2:** Photo taken from the north end of the battery location, facing east. See comments under photo 1.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 323695



**Photo 3:** Photo taken from the battery location. Photo shows vegetation on the location is predominantly undesirable weedy plant species.



**Photo 4:** Photo taken from the adjacent reference area, facing east. Photo shows alfalfa crop in the reference.