

Inspection Photos

07/17/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 331152

Inspection Doc. Number: 682503605

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 331152



Photo 1: Photo taken from the south end of the battery location, facing north. Photo shows equipment remaining on location.



Photo 2: Photo taken from the battery location, facing southwest. Photo shows equipment remaining on location.