

Inspection Photos

07/17/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 329551

Inspection Doc. Number: 682503607

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329551



Photo 1: Photo taken from the battery location, facing south. Photo shows equipment remaining on location.



Photo 2: Photo taken from the well location. Photo shows well remains predominantly bare and exposed soil, or vegetatviely composed of undesirable weedy plant species and is not reflective of the adjacent reference area.



Photo 3: Photo taken from a the adjacent reference area. Reference area is an irrigated hay field with perennial grasses and alfalfa.