

Inspection Photos

07/17/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 318182

Inspection Doc. Number: 682503619

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 318182



Photo 1: Photo taken from the battery location, facing west. Photo shows large areas of the battery location that remains bare and exposed soil. Operator appears to have planted *Echinochloa crus-galli* (Barnyardgrass) at the well and battery location. This is an annual grass that can be weedy according to the USDA, reference area is perennial alfalfa cropland; vegetation is not reflective of the reference area.



Photo 2: Photo taken from the battery location, facing southwest. See comments under photo 1.