

Barrett GM 24-36
Api# 05-045-07502
Inspection # 689701625



Location photo

Barrett GM 24-36
Api# 05-045-07502
Inspection # 689701625



Unmarked anchor.

Barrett GM 24-36
Api# 05-045-07502
Inspection # 689701625



Channeling of edge of ditch.



Channeling of edge of ditch.

Barrett GM 24-36
Api# 05-045-07502
Inspection # 689701625



Erosion of the edge of ditch.



Erosion of the edge of ditch.

Barrett GM 24-36
Api# 05-045-07502
Inspection # 689701625



Ruts washing of road.

Barrett GM 24-36
Api# 05-045-07502
Inspection # 689701625



Ditches on uphill access needs maintained.



Ditches on uphill access needs maintained.