

BARRETT GM 23-36
Api# 05-045-07608
Inspection # 689701627



Location photo

BARRETT GM 23-36
Api# 05-045-07608
Inspection # 689701627



Sediment in ditch on main road just before access road. 39.47601 -108.06135

BARRETT GM 23-36
Api# 05-045-07608
Inspection # 689701627



Sediment in ditch at main and access road intersection.

BARRETT GM 23-36
Api# 05-045-07608
Inspection # 689701627



Sediment in ditch at main and access road intersection.

BARRETT GM 23-36
Api# 05-045-07608
Inspection # 689701627



Washing of road into ditch. Near GM 23-36 location in the back ground.