

Inspection Photos

Location Name: New Cache FH SESE PAD / 8-40D

Location #: 310877



Photo #1

New Cache 8-44 (API 05-123-27176) wellhead



Photo #2

New Cache 8-43, 8-44, Cache 8-54 Battery



Inspection Photos

Location Name: New Cache FH SESE PAD / 8-40D

Location #: 310877



Colorado Oil & Gas Conservation Commission
40.4955, -104.45515, 1394.0m, 176°
2018/07/19 01:34:34 PM

Photo #3

New Cache 8-43, 8-44, Cache 8-54 Battery

No sign with contact info or Emergency # at Batt



Colorado Oil & Gas Conservation Commission
40.49552, -104.45504, 1416.0m, 187°
2018/07/19 01:28:40 PM

Photo #4

New Cache 8-43, 8-44, Cache 8-54 Battery

Stormwater erosion SW of separators



Inspection Photos

Location Name: New Cache FH SESE PAD / 8-40D

Location #: 310877



Photo #5

New Cache 8-43, 8-44, Cache 8-54 Battery

No contents / capacity shown on fiberglass vault



Photo #6

New Cache 8-43, 8-44, Cache 8-54 Battery

Stained soil appears to have dissipated

