

Inspection Photos
Location Name: UPRR 43 PAN AM I #4
Facility ID: 240873



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos
Location Name: UPRR 43 PAN AM I #4
Facility ID: 240873



Photo 3. Weeds around wellhead



Photo 4. Weeds inside tank battery berm and to west side of berm.

Inspection Photos
Location Name: UPRR 43 PAN AM I #4
Facility ID: 240873



Photo 5. Weeds close to emission control device and heated separator.