

Location Name: Bird 13-18 API: 043-06230 Inspection Date: 7/19/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Bird 13-18 API: 043-06230 Inspection Date: 7/19/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Bird 13-18 API: 043-06230 Inspection Date: 7/19/2018



Wellhead. 5 foot by 5 foot stained soil where rig was located.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Bird 13-18 API: 043-06230 Inspection Date: 7/19/2018



Wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Bird 13-18 API: 043-06230 Inspection Date: 7/19/2018



Former tank location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Bird 13-18 API: 043-06230 Inspection Date: 7/19/2018



Tank netting



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Bird 13-18 API: 043-06230 Inspection Date: 7/19/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Bird 13-18 API: 043-06230 Inspection Date: 7/19/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources