

Inspection Photos

Loc#335521

Operator: Vanguard

Inspection Number: 674104550

Inspection Date: 7/14/2018





Photo#1:
Overview of Location from entry to North.

July 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Vanguard JCJ Loc#335521



Photo#2:

One Tamarisk plant was missed or un-affected by control efforts applied in response to CA in previous Reclamation inspection

July 14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Vanguard JCJ Loc#335521